WELL LOG *and* REPORT

In this column indicate the kind of casing, liner, shoe and other accessories used.	WELL DIAGRAM Use a red line to show casing or liner pipe. Use black for drill or borehole.	In this column state the kind of formations penetrated, their thickness in feet and if water bearing.	Record of FINAL Pumping test
Steel Galv Casing	Inches Diameter 2 3 4 5 6 8 10 12 14 16 18 — Depth 25	Clay 47'	Duration of test Hours ____
			Pumping rate G.P.M. ____
			Depth of pump in well, Ft. 293
47	50		
			Standing water-level (from surface) Ft. 265'
	75	Lime Rock 168	Water-level when pumping Ft. 265'
	100		Water. End of test. Clear ✓ Cloudy ____ Turbid ____
	150		Was the well sterilized? Yes ____ No ____
	200	Sand Rock 75'	To which laboratory was sample sent? Madison Date 3-21-1944
		Blue Shale 10'	Was the well sealed on completion? Yes ✓ No ____
	400		
	800		How high did you leave the casing-pipe above grade? 2 ft.
	1200		Well was completed Date 12-1943
	Draw the diagram to show the right half only		Well Driller Carl Williams Signature

CR
1106-2