WELL LOG *and* REPORT

In this column indicate the kind of casing, liner, shoe and other accessories used.	WELL DIAGRAM Use a red line to show casing or liner pipe. Use black for drill or borehole.		In this column state the kind of formations penetrated, their thickness in feet and if water bearing.	Record of FINAL Pumping test

WELL DIAGRAM — Inches / Diameter: 2 3 4 5 6 8 10 12 14 16 18 — Depth: 25, 50, 75, 100, 150, 200, 400, 800, 1200

Draw the diagram to show the right half only

Formations column:

22' HEAVY SOIL AND GRAVEL

SAND

ROCK.

DEPTH = 58' - 5" hole

Left column:

32' STANDARD STEEL CASING

Record of FINAL Pumping test:

Duration of test
Hours __6 hrs__

Pumping rate
G.P.M. __8 gal__

Depth of pump in
well. Ft. __54'__

Standing water-level (from surface)
Ft. __49'__

Water-level when
pumping Ft. __same__

Water. End of test.
Clear __Clear__
Cloudy _____
Turbid _____

Was the well sterilized?
Yes __Yes__ ~~No~~

To which laboratory was sample sent?
__Madison, Wis.__
Date 3:00 P.M. - 4-16-41
also 5-13-41

Was the well sealed on completion?
Yes __Yes__ ~~No~~

How high did you leave the casing-pipe above grade?
__16 "__

Well was completed
Date __3-26-41__

Well Driller
__H. W. Bartels__
Signature

CR
704-2