WELL LOG *and* REPORT

In this column indicate the kind of casing, liner, shoe and other accessories used.	WELL DIAGRAM Use a red line to show casing or liner pipe. Use black for drill or borehole.	In this column state the kind of formations penetrated, their thickness in feet and if water bearing.	Record of FINAL Pumping test
Galv. Casing.		Sand Rock 245 ft.	Duration of test Hours 4 Pumping rate G.P.M. Depth of pump in well. Ft. 278 Standing water-level (from surface) Ft. 245 Water-level when pumping Ft. Water. End of test. Clear — Cloudy Turbid Was the well sterilized? Yes X No To which laboratory was sample sent? M. L. Dean Date 5-28-1943 Was the well sealed on completion? Yes ✓ No How high did you leave the casing-pipe above grade? 2 ft. Well was completed Date 5-14-1943 Well Driller Carl Williams Signature

Draw the diagram to show the right half only

943-2