

WELL LOG and REPORT

In this column indicate the kind of casing, liner, shoe and other accessories used.

WELL DIAGRAM
Use a red line to show casing or liner pipe. Use black for drill or borehole.

In this column state the kind of formations penetrated, their thickness in feet and if water bearing.

Record of **FINAL** Pumping test

46' Star
Steel 5"
Blk
Casing -

Inches Diameter		Depth
2 3 4 5 6 8 10 12 14 16 18		
		25
		50
		75
		100
		150
		200
		400
		800
		1200

LIME

ROCK

AND

CLAY

LIME
ROCK

White
Sand
ROCK

177 feet deep

Draw the diagram to show the right half only

Duration of test
Hours -----

Pumping rate
G.P.M. -----

Depth of pump in well Ft. -----

Standing water-level (from surface)
Ft. -----

Water-level when pumping Ft. -----

Water. End of test.
Clear -----
Cloudy -----
Turbid -----

Was the well sterilized?
Yes yes No -----

To which laboratory was sample sent?
waiting to purchase pump and survey well send sample to Madison

Was the well sealed on completion?
Yes yes No -----

How high did you leave the casing-pipe above grade?
16 inches

Well was completed
Date Oct 18, 1943

Well Driller
H.W. Bartolo
Signature