

WELL LOG and REPORT

For method of making report, refer to bulletin entitled "Well Construction Report," 7-5-39.

In this column indicate the kind of casing, liner, shoe and other accessories used.

WELL DIAGRAM
Use a red line to show casing or liner pipe. Use black for drill or borehole.

In this column state the kind of formations penetrated, their thickness in feet and if water bearing.

Record of
FINAL
Pumping test

33 ft of casing cemented in.
Cement platform.

Inches Diameter		Depth
2 3 4 5 6 8 10 12 14 16 18		
		25
		33
		50
		75
		100
		133 ft.
		150
		200
		400
		800
		1200

20 ft of top Soil + gravel.

113 ft of very hard lime Rock.

Duration of test
Hours 1 hr. Pumping

Pumping rate
G.P.M. 4 gal

Depth of pump in well. Ft. 132

Standing water-level (from surface)
Ft. 112

Water-level when pumping Ft. Waste Using Pumping

Water. End of test.
Clear
Cloudy
Turbid

Was the well sterilized?
Yes No

To which laboratory was sample sent?

state
Date 12/9/41

Was the well sealed on completion?
Yes No

How high did you leave the casing-pipe above grade?
1 ft.

Well was completed
Date Dec 1941

Well Constructor
E. S. Waters
Signature

Draw the diagram to show the right half only

648-2