

WELL LOG and REPORT

For method of making report, refer to bulletin entitled "Well Construction Report," 7-5-39. Accuracy is essential.

In this column indicate the kind of casing, liner, shoe and other accessories used.

WELL DIAGRAM
Use a red line to show casing or liner pipe. Use black for drill or borehole.

In this column state the kind of formations penetrated, their thickness in feet and if water bearing.

Record of FINAL Pumping test

21 ft Blk
Stan Steel
CASING

Inches Diameter		Depth
2 3 4 5 6 8 10 12 14 16		
		25
		50
		75
		100
		150
		200
		400
		800
		1200

Depth

25

50

75

100

150

200

400

800

1200

14'
Chay

225'
of
lime
Rock

SAND Rock.
306' deep

Duration of test
Hours 10 Hrs

Pumping rate
G.P.M. 9 gals

Depth of pump in well. Ft. 297'

Standing water-level (from surface)
Ft. 35'

Water-level when pumping Ft. Same test

Water. End of test.
Clear Clear
Cloudy _____
Turbid _____

Was the well sterilized?
Yes yes No _____

To which laboratory was sample sent?
Madison
Date No Pump
not in use yet.

Was the well sealed on completion?
Yes yes No _____

How high did you leave the casing-pipe above grade?
14 inches

Well was completed
Date June 17, 1943.

Well Constructor
H. W. Bartels
Signature

Draw the diagram to show the full diameter and right section of well only.