

WELL LOG and REPORT

In this column indicate the kind of casing, liner, shoe and other accessories used.

WELL DIAGRAM
Use a red line to show casing or liner pipe. Use black for drill or borehole.

In this column state the kind of formations penetrated, their thickness in feet and if water bearing.

Record of **FINAL** Pumping test

Standard Pipe
Liner Shoe
Cement Grouting

Inches Diameter		Depth
2 3 4 5 6 8 10 12 14 16 18		
		25
		40'
		50
		75
		100
		110'
		150
		200
		225'
		400
		800
		1200

Sand Gravel
20

9 1/2" ?
Liner Pipe
Rock

110'
Sand Rock
Sand Rock
9 5/8" bit

Duration of test
Hours *8 hours*

Pumping rate
G.P.M. *12 gal*

Depth of pump in well. Ft. *215'*

Standing water-level (from surface)
Ft. *160*

Water-level when pumping Ft. *160'*

Water. End of test.
Clear *clear*
Cloudy _____
Turbid _____

Was the well sterilized?
Yes No _____

To which laboratory was sample sent?

Date _____

Was the well sealed on completion?
Yes No _____

How high did you leave the casing-pipe above grade?
2'

Well was completed
Date *Feb 8, 40*

Well Driller
Eugene Miller
Signature

Draw the diagram to show the right half only