

# WELL LOG and REPORT

In this column indicate the kind of casing, liner, shoe and other accessories used.

**WELL DIAGRAM**  
Use a red line to show casing or liner pipe. Use black for drill or borehole.

In this column state the kind of formations penetrated, their thickness in feet and if water bearing.

Record of **FINAL** Pumping test

Standard  
Pipe  
  
Liner  
Shoe  
  
Cement  
Grouting

Inches Diameter											Depth
2	3	4	5	6	8	10	12	14	16	18	
											25
											30
											45
											50
											75
											100
											150
											200
											400
											800
											1200

Sand 30'  
  
Sand Rock 70'

Draw the diagram to show the right half only

Duration of test  
Hours 9 hours

Pumping rate  
G.P.M. 12 GPM

Depth of pump in well. Ft. 90'

Standing water-level (from surface)  
Ft. 50'

Water-level when pumping Ft. 50'

Water. End of test.  
Clear    
Cloudy    
Turbid

Was the well sterilized?  
Yes  No

To which laboratory was sample sent?  
-----

Date -----

Was the well sealed on completion?  
Yes  No

How high did you leave the casing-pipe above grade?  
12"

Well was completed  
Date Sept 3 1939

Well Driller  
Eugene Miller  
Signature