

WELL LOG and REPORT


For method of making report, refer to bulletin entitled "Well Construction Report," 7-5-39. Accuracy is essential.

In this column indicate the kind of casing, liner, shoe and other accessories used.

WELL DIAGRAM
Use a red line to show casing or liner pipe. Use black for drill or borehole.

In this column state the kind of formations penetrated, their thickness in feet and if water bearing.

Record of FINAL Pumping test

Inches Diameter	Depth
2 3 4 5 6 8 10 12 14 16	
	25
	50
	75
	100
	150
	200
	400
	800
	1200

Steel Drive Pipe

*Loose sand
Rock + gravel*

*Solid
white sand
Rock*

Duration of test
Hours *4 hrs*

Pumping rate
G.P.M. _____

Depth of pump in well. Ft. *about 95 ft*

Standing water-level (from surface)
Ft. _____

Water-level when pumping Ft. _____

Water. End of test.
Clear *yes*
Cloudy _____
Turbid _____

Was the well sterilized?
Yes *yes* No _____

To which laboratory was sample sent?
Madison
Date *8 - 1946*

Was the well sealed on completion?
Yes *yes* No _____

How high did you leave the casing-pipe above grade?
2 ft

Well was completed
Date *Aug 1946*

Well Constructor
Carl Wilkman
Signature

Draw the diagram to show the full diameter and right section of well only.