WELL CONSTRUCTOR'S REPORT TO WISCONSIN STATE BOARD OF HEALTH See Instructions on Reverse Side	
_	and the same of th
Section 36 2 mg Do E Tom	(City Check the And Rivers of Themas Company)
3. Owner 🛛 or Agent 🗆 a Color of brems	e or Section, Town and Range numbers
4. Mail Address Lays Mulle, Misconsin R. 7.D.	
Complete address required	
5. From well to nearest: Building 20 ft; sewer 30 ft; drain 30 ft; septic tank 50 ft;	
dry well or filter bed_1 <u>00</u> ft; abandoned well	A
 6. Well is intended to supply water for: \$\frac{\mathcal{T}_{\omega}}{\tau}\$ 7. DRILLHOLE: 	
Dia. (in.) From (ft.) To (ft.) Dia. (in.) From (ft.) To (ft.)	10. FORMATIONS: From To (it.) (it.)
10 0 40 6 40 315	This is an old well
	which I ropaired,
8. CASING AND LINER PIPE OR CURBING: Dia. (in.) Kind and Weight From (ft.) To (ft.)	therefor to not know
6 standard wt 0 40	me formation from
	Blue stone 105 210
9. GROUT:	sandstone 210 315
Kind From (ft.) To (ft.)	
Cement 0 40	Construction of the well was completed on
AND DETECTION TO A TOTAL	Construction of the well was completed on: 1956
11. MISCELLANEOUS DATA:	The well is terminated
Yield test: Hrs. at GPM.	above, below [] the permanent ground surface.
Depth from surface to water-level: ft.	Was the well disinfected upon completion?
Water-level when pumping: ft. Water sample was sent to the state laboratory at:	Yes.,X No
Madison on April 1956	Was the well sealed watertight upon completion?
	Yes_X No
Registered Well Diller	P.3 Boy 36 Boochel, a Complete Mail Address
Rec'd APR 24 1956 No. 11007	· · · · · · · · · · · · · · · · · · ·
Ans'd	Gas—24 hrs
Interpretation	48 hrs.
·	Confirm
·	B. Coli