

WELL LOG and REPORT

In this column indicate the kind of casing, liner, shoe and other accessories used.

WELL DIAGRAM
Use a red line to show casing or liner pipe. Use black for drill or borehole.

In this column state the kind of formations penetrated, their thickness in feet and if water bearing.

Record of
FINAL
Pumping test

*Std. Wt. Pipe
Well Drillers
Special*

Inches Diameter		Depth
2 3 4 5 6 8 10 12 14 16 18		
		25
		50
		75
		100
		150
		200
		400
		800
		1200

*35 ft.
Gravel*

Sand Rock

Blue Shale

76

Duration of test
Hours *7*

Pumping rate
G.P.M. _____

Depth of pump in well. Ft. *63*

Standing water-level (from surface)
Ft. *32*

Water-level when pumping Ft. *32*

Water. End of test.
Clear
Cloudy _____
Turbid _____

Was the well sterilized?
Yes _____ No _____

To which laboratory was sample sent?

Madison
Date *3-21-1944*

Was the well sealed on completion?
Yes *A* No _____

How high did you leave the casing-pipe above grade?
1 ft

Well was completed
Date *2-17-1944*

Well Driller
Carl William
Signature

Draw the diagram to show the right half only