## WELL LOG and REPORT

For method of making report, refer to bulletin entitled "Well Construction Report," 7-5-39. Accuracy is essential. WELL DIAGRAM Record of In this column state the kind of In this column indicate the kind Use a red line to show casing FINAL formations penetrated, their thickness in of casing, liner, shoe and other or liner pipe. Use black for drill Pumping test feet and if water bearing. accessories used. or borehole. Diameter Inches Depth 64 of 5' Standard 2 3 4 5 6 8 10121416 Duration of test
Hours 10 hus DIRE SAND Steel Blk Casing Pumping rate
G.P.M. Sgala WATER Depth of pump in well. Ft. 23 feet 50 Standing water-level (from surface) Ft. /8 um Depth of well 76 Leet. SAKD ROCK Water-level when 75 pumping Ft. Same Water. End of test. Clear Clear 100 Cloudy Turbid\_\_\_\_\_ Was the well sterilized? Yes yes No. 150 To which laboratory was sample Madison 200 Was the well scaled on completion? 400 How high did you leave the casing-pipe above grade? Pit with suction pump. 800 Well was completed Date Sept 13, 1943 1200 Well Constructor
H.W. Barlels Draw the diagram to show the full diameter and right section of well only.

cr 349-2