

WELL CONSTRUCTOR'S REPORT TO WISCONSIN STATE BOARD OF HEALTH

Wol 6

See Instructions on Reverse Side

RECEIVED

DEC 27 1964

SANITARY ENGINEERING

1. County Crawford Town  Seneca  
Village   
City  Check one and give name

2. Location at SE 1/4 of SE 1/4 lot 4 Sec 35 - T5P16 - R6W  
Name of street and number of premise or Section, Town and Range numbers

3. Owner  or Agent  Horace Mechel  
Name of individual, partnership or firm

4. Mail Address Lynnville  
Complete address required

5. From well to nearest: Building 8 ft; sewer \_\_\_\_\_ ft; drain \_\_\_\_\_ ft; septic tank \_\_\_\_\_ ft;  
 dry well or filter bed \_\_\_\_\_ ft; abandoned well \_\_\_\_\_ ft.

6. Well is intended to supply water for: Trailer

7. DRILLHOLE:

Dia. (in.)	From (ft.)	To (ft.)	Dia. (in.)	From (ft.)	To (ft.)
10	top	43	5 1/2	45	120

8. CASING AND LINER PIPE OR CURBING:

Dia. (in.)	Kind and Weight	From (ft.)	To (ft.)
5	15# Steel	43	43

9. GROUT:

Kind	From (ft.)	To (ft.)
Cement	43	50

11. MISCELLANEOUS DATA:

Yield test: 8 Hrs. at 10 GPM.  
 Depth from surface to water-level: 70 ft.  
 Water-level when pumping: 84 ft.  
 Water sample was sent to the state laboratory at:  
Madison on 12/14 1964  
City

10. FORMATIONS:

Kind	From (ft.)	To (ft.)
Clay	top	20
Substructure	20	30
Sandstone	30	120

Construction of the well was completed on: 10/16 1964

The well is terminated 14 inches  above, below  the permanent ground surface.

Was the well disinfected upon completion?  
 Yes  No

Was the well sealed watertight upon completion?  
 Yes  No

Signature Edwin Wray  
 Registered Well Driller

New Albany, Iowa  
 Complete Mail Address

Please do not write in space below

Rec'd DEC 15 1964 No. 57520

Ans DEC 17 1964

Interpretation \_\_\_\_\_

SAFE BACTERIOLOGICALLY

10 ml 10 ml 10 ml 10 ml 10 ml

Gas—24 hrs. \_\_\_\_\_

48 hrs. \_\_\_\_\_

Confirm \_\_\_\_\_

B. Coli 00000

Examiner \_\_\_\_\_