

WELL CONSTRUCTOR'S REPORT

Well-6

SEP 21 1970

STATE OF WISCONSIN
DEPARTMENT OF NATURAL RESOURCES
Box 450
Madison, Wisconsin 53701

WHITE COPY - DIVISION'S COPY
GREEN COPY - DRILLER'S COPY
YELLOW COPY - OWNER'S COPY

1. COUNTY Crawford CHECK ONE Town Village City NAME Marietta

2. LOCATION (Number and street or 1/4 section, section, township and range. Also give subdivision name, lot and block numbers when available.)
SE 1/4 of Sec. 3 T7N R4W

3. OWNER AT TIME OF DRILLING
John C. Roesslet

4. OWNER'S COMPLETE MAIL ADDRESS
R2 Boscobel, Wis., 53805

5. Distance in feet from well to nearest: (Record answer in appropriate block)

BUILDING	SANITARY SEWER	FLOOR DRAIN	FOUNDATION DRAIN	WASTE WATER DRAIN
	C.I.	TILE	C.I.	TILE
			SEWER CONNECTED	INDEPENDENT
				C.I.
				TILE

60'

CLEAR WATER DRAIN	SEPTIC TANK	PRIVY	SEEPAGE PIT	ABSORPTION FIELD	BARN	SILLO	ABANDONED WELL	SINK HOLE
C.I.	TILE							

75'

OTHER POLLUTION SOURCES (Give description such as dump, quarry, drainage well, stream, pond, lake, etc.)

6. Well is intended to supply water for: Livestock

7. DRILLHOLE						10. FORMATIONS			
Dia. (in.)	From (ft.)	To (ft.)	Dia. (in.)	From (ft.)	To (ft.)	Kind	From (ft.)	To (ft.)	
<u>10</u>	<u>Surface</u>	<u>72</u>	<u>6</u>	<u>72</u>	<u>300</u>	<u>Clay</u>	<u>Surface</u>	<u>60</u>	
						<u>limestone</u>	<u>60</u>	<u>72</u>	

8. CASING, LINER, CURBING, AND SCREEN			
Dia. (in.)	Kind and Weight	From (ft.)	To (ft.)
<u>6</u>	<u>new black steel</u>	<u>Surface</u>	<u>72</u>
	<u>plain end 19.18</u>	<u>0</u>	<u>72</u>

I do not know the formations below this point, this was a re-case job

9. GROUT OR OTHER SEALING MATERIAL		
Kind	From (ft.)	To (ft.)
<u>Clay</u>	<u>Surface</u>	<u>60</u>
<u>Cement</u>	<u>60</u>	<u>72</u>

Well construction completed on 7-10-1970

11. MISCELLANEOUS DATA

Yield test: 2 Hrs. at 10 GPM

Well is terminated 12 inches above below final grade

Depth from surface to normal water level 250 ft. Well disinfected upon completion Yes No

Depth to water level when pumping 253 ft. Well sealed watertight upon completion Yes No

Water sample sent to Madison laboratory on: 9-16-1970

Your opinion concerning other pollution hazards, information concerning difficulties encountered, and data relating to nearby wells, screens, seals, type of casing joints, method of finishing the well, amount of cement used in grouting, blasting, sub-surface pumphrooms, access pits, etc., should be given on reverse side.

SIGNATURE Henneth Copian Registered Well Driller COMPLETE MAIL ADDRESS R3 Box 84 Boscobel, Wis. 53805

Please do not write in space below

COLIFORM TEST RESULT <u>332</u>	GAS - 24 HRS.	GAS - 48 HRS.	CONFIRMED	REMARKS
------------------------------------	---------------	---------------	-----------	---------