

DRILLER'S REPORT

15

NOTE

WHITE COPY - DIVISION'S COPY
 GREEN COPY - DRILLER'S COPY
 YELLOW COPY - OWNER'S COPY

STATE OF WISCONSIN
 DEPARTMENT OF NATURAL RESOURCES
 Box 460
 Madison Wisconsin 53701

COUNTY Crawford CHECK ONE Town Village City NAME Clayton

2. LOCATION - 1/4 Section NW Section 9 Township 10N Range 3W

OR - Grid or street no. Street name

AND - If available subdivision name, lot & block no.

3. OWNER AT TIME OF DRILLING Jim Bacon
 ADDRESS R7D
 POST OFFICE Soldiers Grove Wis 54655

4. Distance in feet from well to nearest:

BUILDING	SANITARY SEWER	FLOOR	RAIN	FOUNDATION DRAIN	WASTE WATER DRAIN
C.I.	C.I.	C.I.	TILE	SEWER CONNECTED	INDEPENDENT
	<u>25'</u>	<u>40'</u>		<u>40'</u>	

CLEAR WATER DRAIN	SEPTIC TANK	PRIVY	SEEPAGE PIT	ABSORPTION FIELD	BARN	SILLO	ABANDONED WELL	SINK HOLE
C.I.	TILE							
	<u>65'</u>			<u>90'</u>				

OTHER POLLUTION SOURCES (Give description such as dump, quarry, drainage well, stream, pond, lake, etc.)

5. Well is intended to supply water for: Country home

6. DRILLHOLE

Dia. (in.)	From (ft.)	To (ft.)	Dia. (in.)	From (ft.)	To (ft.)
<u>10</u>	<u>0</u> Surface	<u>143</u>	<u>6</u>	<u>143</u>	<u>300</u>

9. FORMATIONS

Kind	From (ft.)	To (ft.)
<u>Clay</u>	<u>0</u> Surface	<u>40</u>
<u>broken limestone</u>	<u>40</u>	<u>120</u>
<u>hard sandstone</u>	<u>120</u>	<u>300</u>

7. CASING, LINER, CURBING, AND SCREEN

Dia. (in.)	Kind and Weight	From (ft.)	To (ft.)
<u>6</u>	<u>new black steel plain end 18.97</u>	<u>0</u> Surface	<u>143</u>

8. GROUT OR OTHER SEALING MATERIAL

Kind	From (ft.)	To (ft.)
<u>puddled clay</u>	<u>0</u> Surface	<u>40</u>
<u>Cement</u>	<u>40</u>	<u>143</u>

10. TYPE OF DRILLING MACHINE USED

Cable Tool Direct Rotary Reverse Rotary

Rotary - air w/drilling mud Rotary - hammer with drilling mud & air Jetting with Air Water

Well construction completed on 11-10-75

Well is terminated 10 inches above below final grade

Well disinfected upon completion Yes No

Well sealed watertight upon completion Yes No

Water sample sent to Madison laboratory on: 11-24-75

Our opinion concerning other pollution hazards, information concerning difficulties encountered, and data relating to nearby wells, screens, seals, type of casing joints, method of finishing the well, amount of cement used in grouting, blasting, sub-surface pump-problems, access pits, etc., should be given on reverse side.

NATURE Kenneth Corpiar Registered Well Driller

COMPLETE MAIL ADDRESS R3 Box 84 Boscobel, Wis. 53805

FORM TEST RESULT

GAS - 24 HRS.	GAS - 48 HRS.	CONTAMINATED	REMARKS
<u>858</u>			